

March 28, 2005

PG&E Letter DCL-05-029

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Docket No. 50-323, OL-DPR-82
Diablo Canyon Unit 2
Licensee Event Report 2-2005-001-00
Technical Specification 3.4.10 Not Met During Pressurizer Safety Valve
Surveillance Testing Due to Random Lift Spread

Dear Commissioners and Staff:

In accordance with 10 CFR 50.73(a)(2)(i)(B), PG&E is submitting the enclosed licensee event report regarding the pressurizer code safety valves being outside the Technical Specification 3.4.10 set pressure due to random lift spread.

This event was not considered risk significant and did not adversely affect the health and safety of the public.

Sincerely,

David H. Oatley

ddm/2246/A0630775

Enclosure

cc/enc: Bruce S. Mallett
David L. Proulx
Girija S. Shukla
INPO
cc: Diablo Distribution

NRC FORM 366 (6-2004)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104 Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.		EXPIRES: 06/30/2007						
<h2 style="margin: 0;">LICENSEE EVENT REPORT (LER)</h2> <p style="margin: 5px 0 0 40px;">(See reverse for required number of digits/characters for each block)</p>												
1. FACILITY NAME Diablo Canyon Unit 2					2. DOCKET NUMBER 05000323		3. PAGE 1 OF 5					
4. TITLE TS 3.4.10 Not Met During Pressurizer Safety Valve Surveillance Testing Due to Random Lift Spread												
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME		DOCKET NUMBER	
01	27	2005	2005	- 001 -	00	03	28	2005	FACILITY NAME		DOCKET NUMBER	
											05000	
											05000	
9. OPERATING MODE <div style="text-align: center; font-size: 24px;">1</div>		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: <i>(Check all that apply)</i>										
		<input type="checkbox"/> 20.2201(b) <input type="checkbox"/> 20.2201(d) <input type="checkbox"/> 20.2203(a)(1) <input type="checkbox"/> 20.2203(a)(2)(i) <input type="checkbox"/> 20.2203(a)(2)(ii) <input type="checkbox"/> 20.2203(a)(2)(iii) <input type="checkbox"/> 20.2203(a)(2)(iv) <input type="checkbox"/> 20.2203(a)(2)(v) <input type="checkbox"/> 20.2203(a)(2)(vi)		<input type="checkbox"/> 20.2203(a)(3)(i) <input type="checkbox"/> 20.2203(a)(3)(ii) <input type="checkbox"/> 20.2203(a)(4) <input type="checkbox"/> 50.36(c)(1)(i)(A) <input type="checkbox"/> 50.36(c)(1)(ii)(A) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.46(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(i)(A) <input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)		<input type="checkbox"/> 50.73(a)(2)(i)(C) <input type="checkbox"/> 50.73(a)(2)(ii)(A) <input type="checkbox"/> 50.73(a)(2)(ii)(B) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(iv)(A) <input type="checkbox"/> 50.73(a)(2)(v)(A) <input type="checkbox"/> 50.73(a)(2)(v)(B) <input type="checkbox"/> 50.73(a)(2)(v)(C) <input type="checkbox"/> 50.73(a)(2)(v)(D)		<input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/> 50.73(a)(2)(ix)(A) <input type="checkbox"/> 50.73(a)(2)(x) <input type="checkbox"/> 73.71(a)(4) <input type="checkbox"/> 73.71(a)(5) <input type="checkbox"/> OTHER				
10. POWER LEVEL <div style="text-align: center; font-size: 24px;">100</div>		Specify in Abstract below or in NRC Form 366A										
12. LICENSEE CONTACT FOR THIS LER												
FACILITY NAME Lawrence M. Parker – Senior Regulatory Services Engineer								TELEPHONE NUMBER (Include Area Code) (805) 545- 3386				
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT												
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX			
X	AB	RV	C710	Yes								
14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES <i>(If yes, complete 15. EXPECTED SUBMISSION DATE)</i> <input checked="" type="checkbox"/> NO								15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR
ABSTRACT <i>(Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)</i>												
<p>On January 27, 2005, during scheduled testing in accordance with Surveillance Test Procedure M-77, "Safety and Relief Valve Testing," PG&E identified two of three pressurizer safety valves (PSVs) outside the Technical Specification (TS) 3.4.10, "Pressurizer Safety Valves, ... lift setting of ≥ 2460 and ≤ 2510 psig." The as-found lifts were 4.4 and 3.6 percent low, and within analyzed safety limits; thus, this condition did not adversely affect the health and safety of the public.</p> <p>The PSVs were disassembled, inspected, and reset within the TS 3.4.10 lift setpoint requirements. PG&E believes the cause of the PSVs being outside the TS allowance is random lift spread.</p> <p>PSV lift setting repeatability has been recognized as an industry-wide problem. PG&E has participated in extensive investigative test programs, both jointly with the nuclear steam supply system vendor, Westinghouse Owners Group, and independently. The results of the industry investigations are documented in WCAP-12910, "Pressurizer Safety Valve Set Pressure." PG&E has previously enhanced the PSV maintenance activities and testing procedures resulting in improved performance. No further corrective actions are required.</p>												

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)								LER NUMBER (6)						PAGE (3)		
									YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2005	-	0	0	1	-	0	0	2 OF 5

TEXT

I. Plant Conditions

Unit 2 has operated in various plant modes with the described condition.

II. Description of Problem

A. Background

TS 3.4.10, "Pressurizer Safety Valves," requires that three PSVs [AB][RV] shall be operable with a lift setting greater than 2460 psig and less than 2510 psig corresponding to ambient conditions of the valve at nominal operating temperature and pressure. This upper and lower pressure limit is based on a nominal pressure of 2485 psig, with an upper and lower tolerance limit of plus or minus one percent.

Surveillance Test Procedure (STP) M-77, "Safety and Relief Valve Testing," verifies the PSV's lift setting in accordance with the requirements of the ASME Boiler and Pressure Vessel Code, Section XI. The initial (as-found) lift setting is evaluated for TS compliance. STP M-77 requires that the valves lift within the required tolerance in order to declare them operable.

STP M-77 test methodology obtains the as-found lift setting by placing the PSVs in an environmentally controlled enclosure and heating the ambient air to the temperature conditions typical at Diablo Canyon Power Plant (DCPP). The loop seal is also heated to simulate the piping temperature conditions at DCPP. Testing is accomplished by the addition of steam at a defined ramp rate. Steam is added until physical evidence of stem movement is visible on the remote data acquisition display screen. The data is then reviewed to ascertain "first discernible stem movement" and the pressure at which it took place.

B. Event Description

Following the Unit 1 eleventh refueling outage (1R11) in May 2002, the subject PSVs lift settings were verified to be within the range required by TS 3.4.10. The PSVs were then returned to warehouse stock. During the Unit 2 eleventh refueling (2R11) outage in February 2003, these three PSVs were placed in service in Unit 2 without any additional adjustment of the lift settings. The valves were replaced during 2R12 in November 2004 and tested offsite in January 2005.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)							PAGE (3)		
										YEAR	SEQUENTIAL NUMBER					REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2005	-	0	0	1	-	0	0	3	OF	5

TEXT

On January 27, 2005, during scheduled offsite testing in accordance with STP M-77, "Safety and Relief Valve Testing," PG&E identified two of three PSVs outside the TS 3.4.10, "Pressurizer Safety Valves, ... lift setting of ≥ 2460 and ≤ 2510 psig." The initial lift settings were 4.4 and 3.6 percent low. The second valve lifts of these same two PSVs were found to be 3.1 percent low and 0.3 percent low, respectively.

PSV lift setting repeatability has been recognized as an industry-wide problem. PG&E has participated in extensive investigative test programs, both jointly with the nuclear steam supply system vendor, Westinghouse Owners Group, and independently. The results of the industry investigations are documented in WCAP – 12910, "Pressurizer Safety Valve Set Pressure."

C. Inoperable Structures, Systems, or Components that Contributed to the Event

None.

D. Other Systems or Secondary Functions Affected

None.

E. Method of Discovery

This condition was identified during routine scheduled testing performed in accordance with STP M-77 at the offsite testing facility.

F. Operator Actions

None.

G. Safety System Responses

None.

III. Cause of the Problem

A. Immediate Cause

Two of three PSVs did not lift within the TS 3.4.10 lift-setting tolerance.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)								LER NUMBER (6)						PAGE (3)		
									YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2005	-	0	0	1	-	0	0	4 OF 5

TEXT

B. Root Cause

The cause of the as-found lift setting has been determined to be random lift spread.

C. Contributory Cause

None.

IV. Assessment of Safety Consequences

The limiting event for evaluating the lift setting is the loss of load analysis that requires the maximum reactor coolant system (RCS) pressure of 2750 psia not be exceeded. The RETRAN computer model was run to determine if, with the as-found PSV lift setpoint, the RCS pressure would exceed 110 percent of ASME design acceptance criteria, or 2750 psia. The analysis confirmed that the as-found set points would have maintained adequate RCS pressure relief capacity, such that the plant remained bounded by the limiting loss of load analysis provided in Final Safety Analysis Report Update, Section 15.2.7, "Loss of External Electrical Load and/or Turbine Trip." Also, the as-found lift setting was reviewed for potential interaction with the pressurizer power-operated relief valves (PORVs) and the potential for inadvertent low pressure lifting, and were found acceptable.

Therefore, this event was of very low risk significance, was not a Safety System Functional Failure, and did not adversely affect the health and safety of the public.

V. Corrective Actions

A. Immediate Corrective Actions

The valves were disassembled, inspected, reset within tolerance, and returned to warehouse stock.

B. Corrective Actions to Prevent Recurrence

No corrective action to prevent recurrence is required because the inherent characteristics of the valve are within the safety analysis basis of DCPD.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2005	-	0	0	1	-	0	0	5	OF 5

TEXT

VI. Additional Information

A. Failed Components

None.

B. Previous Similar Events

LER 1-94-009, Revision 2, submitted in PG&E Letter DCL-95-248, dated November 7, 1995, regarding PSVs found outside TS limits during the Unit 1 sixth refueling outage. The root cause of this event was determined to be random lift-setting spread. No corrective action to prevent recurrence was required because this inherent characteristic of the valve was within the analysis basis of DCP. However, a prudent action to replace the PSV upper spring washer was recommended. The implementation of this prudent action has been deferred until NRC concerns regarding valve performance can be acceptably resolved.

LER 1-95-016, Revision 2, submitted in PG&E Letter DCL-98-077, dated May 28, 1998, regarding PSVs found outside TS limits during the Unit 1 seventh refueling outage. The root cause of this event was determined to be random lift-setting spread. No corrective action to prevent recurrence was required because this inherent characteristic of the valve was within the analysis basis of DCP. However, a prudent action to replace the PSV upper spring washer was recommended. The implementation of this prudent action has been deferred until NRC concerns regarding valve performance can be acceptably resolved.

LER 2-2001-004, submitted in PG&E Letter DCL-01-090, dated August 27, 2001, regarding one PSV found 3.4 percent low and one PSV found 2.8 percent high during offsite testing. The root cause of this event was determined to be random lift-setting spread. No corrective action to prevent recurrence was required because this inherent characteristic of the valve was within the analysis basis of DCP.

LER 1-2002-005-00, submitted in PG&E Letter DCL-02-091, dated August 9, 2002, regarding one PSV found 1.9 percent low and one PSV found 2.6 percent high during offsite testing. The root cause of this event was determined to be random lift-setting spread. No corrective action to prevent recurrence was required because this inherent characteristic of the valve was within the analysis basis of DCP.

OUTGOING CORRESPONDENCE SCREEN

(Remove prior to NRC submittal)

Document: PG&E Letter DCL-05-029

Subject: TS 3.4.10 Not Met During Pressurizer Safety Valve Surveillance Testing
Due to Random Lift Setting Spread

File Location S:\RS\RAILER\2005\2005-001-00.doc

FSAR Update Review

Utilizing the guidance in XI3.ID2, does the FSAR Update need to be revised? Yes ☐ No ☒
If "Yes", submit an FSAR Update Change Request in accordance with XI3.ID2 (or if this is an LAR, process in accordance with WG-9)

Commitment #1

Statement of Commitment: None.

Clarification.

<i>Tracking Document:</i>	<small>AR or NCR</small> A0630775	<small>AE or ACT</small> AE01
<i>Assigned To:</i>	<small>NAME</small> Don Malone	<small>ORGANIZATION CODE</small> PTRB
<i>Commitment Type:</i>	<small>FIRM OR TARGET</small> Firm	<small>DUE DATE:</small> 03/28/2005
<i>Outage Commitment?</i>	<small>YES OR NO</small> No	<small>IF YES, WHICH? (E.G., 2R9, 1R10, ETC.)</small>
<i>PCD Commitment?</i>	<small>YES OR NO</small> No	<small>IF YES, LIST THE IMPLEMENTING DOCUMENTS (IF KNOWN)</small>
<i>Duplicate of New NCR Commitment in PCD?</i>	<small>YES OR NO</small>	<small>IF YES, LIST PCD NUMBER (e.g., T35905, etc.)</small>
<i>Old PCD Commitment being changed?</i>	<small>YES OR NO</small>	<small>IF YES, LIST PCD NUMBER, AND CLARIFY TO CLERICAL HOW COMMITMENT TO BE REVISED</small>